













F						REV.	ECN NO.	DATE	SIGN	DESCRIPTION		
						B	LE31770038	2017-07-04	Fisher Wang	Change Note,add 6 Tee connector and Package		
						C	LEN1781512	2017-08-17	Frank Deng	Update Note		
						CA	C230552	2023-05-12	Ruru	 CA XI		
E	Basic	 ① HMC-050505-FFM-TS001	3 Tee Adaptor 2Pcs									
		② HMC-05BFFT-SL8001	Female Terminator 1Pcs									
		③ HMC-05BMMT-SL8001	Male Terminator 1Pcs									
		⑤ HMC-050500-FM0-TSA02	T Cable, 2M 1Pcs									
		④ HMC-000505-OMF-CSA02	Drop Cable Cable Length=2M, 1Pcs									
					 Note: * 3 Tee Adaptor: 2PCS * Female Terminitor 1PCS * Male Terminitor :1PCS * T-Cable, cable length 2m, 1PCS * 2 Ends Cable, cable length 2m, 1PCS * All connector put into the blister tray * 注意繞線尺寸需符合圖面要求, 否則會影響產品裝入彩盒. * 5pcs blister tray /Carton * Net weight: 2.0kg / Carton * Gross weight: 4.2Kg / Carton							
A	UNIT:mm	 	TITLE NMEA2000 Starter Kit Metal, Basic Type		Amphenol LTW 安費諾亮泰企業股份有限公司		ITEM NO	HMC-B-001	DRAWN BY	Frank Deng	DATE	2017-08-17
	TOLERANCE	SCALE Free SIZE A4 SHEET 1 OF 2		DWG NO			HMC-B-001	CHECKED BY	Fisher Wang	DATE	2017-08-17	
	REV. CA WC-REV. A.2	QC:Inspection item	CUSTOMER	ALTW			APPROVED BY	Kevin Hu	DATE	2017-08-17		
	8 W10814-03-0001A2											


△ Package:




Step 1: Connector put in the Tray
將所有連接器裝入泡殼




Step 2: Use adhesive tape bonding the blister tray and cover
使用膠帶粘合泡殼和上蓋




Step 3: First the cable into the paper box, then put the blister tray into the paper box
先將線材放入紙盒，然後再將裝好連接器的泡殼放入紙盒



Step 4: Use a small circular stickers on cartons side, small circular sticker must be on the right product, and then do shrink film
使用一張圓形小貼紙貼于紙盒側邊，圓形貼紙需貼在正確的產品料號上，確認紙盒內部包裝的產品與圖面要求一致，然後封收縮膜包裝



Step 5: First put a waterproof bag into carton, 5pcs paper box into the carton, use air bag filling the gaps
首先在外箱內放一個防水袋，每5個紙盒裝入一個外箱，多餘的空隙需用氣袋填滿



UNIT:mm
TOLERANCE

TITLE NMEA2000 Starter Kit Metal, Basic Type			
SCALE Free	SIZE A4	SHEET 2 OF 2	
REV. CA	WC-REV. A.1	QC: Inspection item	

Amphenol LTW
安費諾亮泰企業股份有限公司

ITEM NO HMC-B-001	DRAWN BY Frank Deng	DATE 2017-08-17
DWG NO HMC-B-001	CHECKED BY Fisher Wang	DATE 2017-08-17
CUSTOMER ALTW	APPROVED BY Kevin Hu	DATE 2017-08-17